

Dr. Martin LeBoldus Catholic High School

2330 – 25th Ave. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: November 2010

1. Type of Asbestos-	2. Location in	3. Characteristics	4. Accessibility	5. Comments
Containing Material	Facility			
Chrysotile	Boiler room	Pipefitting Compound 60-80%	Behind locked door Maintenance only	All accessible locations marked with RED spray paint. All other locations assumed to
		00-80%	ivialite lance only	have ACM
Chrysotile	Boiler room-	Parging Compound	Behind locked door	All accessible locations marked with RED
	Tanks, vessels & ducts	60-70%	Maintenance only	spray paint. All other locations assumed to have ACM
Chrysotile	Throughout Building	Rain water leader		All accessible locations marked with RED
Crocidolite		CH20% CR5%		spray paint. All other locations assumed to have ACM
Chrysotile	Room 271-	Panel Liner	Exposed	In good condition, recommended to manage
	Fume hood	60%	Non-friable	in place until renovation warrants removal.
				Not marked for visibility purposes
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have
				ACM