

St. Michael

431 Hamilton St. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: October 2012

1. Type of Asbestos-	2. Location in	3. Characteristics	4. Accessibility	5. Comments
Containing Material	Facility			
Chrysotile	Throughout building	Stipple ceiling texture	Most Above ceiling	**CEILING TILES SHOULD NOT BE MOVED
		20%	tiles. Some exposed	THROUGHOUT THIS FACILITY**
Chrysotile	Mechanical Rooms	Pipefitting Compound	Behind locked door	All accessible locations marked with RED spray
		20%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Corridor	Duct expansion	Above ceiling tiles	All accessible locations marked with RED spray
		Canvas 25%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Corridor	Duct tape	Above ceiling tiles	All accessible locations marked with RED spray
		5%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Throughout building	Pipefitting Compound	Above ceiling tiles	All accessible locations marked with RED spray
		40-80%	Maintenance only	paint. All other locations assumed to have ACM
Chrysotile	Throughout building	Transite Rainwater		All locations assumed to have ACM
		Leader 30%		
Chrysotile	Mother Theresa	Flooring	Sealed floor	Moderate condition and recommended to manage
	Storage room	1-5%		in place until renovation warrants removal
Chrysotile	Main entrance	Flooring	Sealed floor	Moderate condition and recommended to manage
		30%		in place until renovation warrants removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM
		1		