

St. Bernadette

727 N McIntosh Ave. Regina, Sk.

Contact Person: Tyler Ottenbreit Title: Facilities Supervisor Telephone: 306-791-7213 Email: t.ottenbreit@rcsd.ca

Date of Inventory: May 2013

Type of Asbestos- Containing Material	Location in Facility	3. Characteristics	4. Accessibility	5. Comments
Chrysotile	Basement – Boiler Room	Duct expansion gasket 30%	Behind locked doors Maintenance only	All accessible locations marked with RED spray paint. There may also be more under the yellow insulation
Chrysotile	Throughout building	Transite Rainwater Leader CH-30%		All locations assumed to have ACM
Chrysotile	Nurses room	Flooring 35%	Sealed floor	Moderate condition and recommended to manage in place until renovation warrants removal
Vermiculite	Throughout	Block walls		All concrete block walls are assumed to have ACM